IMPORTANT

You must place the provided insulators into the unused MB plate punch-ups to avoid shortage.

Place motherboard (MB) on MB plate as you would place for installation.
Place provided insulator(s) into unused punch-ups that are covered by the MB as shown below. Secure MB to MB plate with provided screws.



PART NUMBER 3130(P4) ATX CASE



P4-TP13*10L*4 SCREW

*4PCS

Iteme	Diagram	PartsDescription	QTY	Iteme	Diagram	PartsDescription	QTY	Iteme	Diagram	PartsDescription	QTY	Iteme	Diagram	Parts Description	QTY
1		I/OPANEL/PCI#6*32SCREW	1/1	3		#6*32*6L SCREW	9	5 6		CD-ROM FDD M3*4 SCREW	12	10		Insulated	6
2		PCB SPACER	1	4		RUBBER FOOT	4	7		HDD#6*32 SCREW	4				